Order #XXXXX MOD-1331 Workstation

Steps:
1) Attach lower verticals [2] and [3] to base plate [1], using bolts.
2) Attach upper vertical [4] to lower vertical [2], using connector.
3) Attach shelves to vertical [2].
4) Attach large graphic to verticals [3], using screw caps. See Large Graphic Attachment detail.
5) Attach flange plates [5] to tops of verticals [3], using bolt.
6) Attach counter to flange plates [5] vertical [2], using wing nuts and thumb screws. See Counter Attachment detail.
7) Attach small and curved graphics to [4], using A10 clamps. See A10 Clamp detail.
8) Attach monitor mount to [4]. See Monitor Mount detail.

Item	Qty.	Description
1	1	Base Plate
2	1	48” Q914 Vertical Extrusion
3	2	38” Z45 Vertical Extrusion
4	1	25” Q914 Vertical Extrusion w/ Cap, Clamps, and Connector
5	2	Flange Plate
--	3	Shelf



✱ A10 Clamp

Tighten set screw to secure A10 to [4].



Tighten knob to secure graphic to A10 Clamp.

Keep A10 clamps attached to [4] when packing.

Keep connector with set screws attached to [2] when packing.







Completed Assembly

✱ Large Graphic Attachment



Slide V4 into Z45 then tighten set screw. Secure graphic to V4, using screw cap.

✱ Counter Attachment



Attach flange plates to extrusions [4], using screws. Insert fixed screws, on counter, into holes of flange plate then secure with wing nuts. Secure back of counter, using thumb screws.

✱ Monitor Mount Attachment

Attach Monitor Mount back piece to vertical extrusion using bolts & nuts.



Slide monitor mount into back piece.

Slide connectors into groove of extrusion. Tighten set screws to secure connectors in place. Attach monitor mount back plate to extrusion, using bolts.

SETUP INSTRUCTIONS

General Setup Instructions

- Read entire setup instruction manual prior to unpacking parts and pieces.

- The setup instructions are created specifically for this configuration.

- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a **MILD NON-ABRASIVE** cleanser and soft cloth/paper towel to clean all surfaces.

- Keep exhibit components away from heat and prolonged sun exposure.
Heat and UV exposure will warp and fade components.

- Retain all provided Packing Materials.
All provided packing materials are for ease of repacking & component protection.

Disassembly

- For loss prevention, tighten all set screws and locks during disassembly.



Hex Tool - Essential for Assembly



Part Identification - Numbering



Spline Connection



Base Plate & Extrusion Connection



Extrusion & Lock Connection



Engaged Lock

WARNING

DO NOT USE POWER TOOLS

LADDERS OR LIFTS MAY BE REQUIRED

ALL CONNECTIONS MUST BE TIGHTLY SECURED

Top View of Each Level



Level 1
(Bottom level)



Level 2



Level 3



Level 4



Level 5